

ERA23LA198

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to the right wingtip (Courtesy of FAA)



Photograph 2 - View of aileron trailing edge damage. (Courtesy of FAA)



Photograph 3 - View of right wing rib and aileron damage. (Courtesy of FAA)