



Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA199



Photo 1 – View of airplane from left wing (Photo courtesy of FAA)



Photo 2 – Close-up view of left wing leading edge damage (Photo courtesy of FAA)