

ERA23LA202

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Larger tear on check valve O-ring



Photograph 2 - Smaller tear on check valve O-ring