

ERA23LA202

AIRCRAFT MAINTENANCE LOG ENTRY - HYDRAULIC PACK



Model ROCKWELL COMMANDER 112A
Registration N12RX
S/N 270

Date: 11/05/2022

Tach: 3,042.65

1. REMOVED HYD SYS POWER PACK UNIT PN HYC 5001 SN AH-2379. INSTALLED OVERHAULED HYD SYS POWER PACK UNIT PN HYC 5001 SN AH-5707 (8130-3 ATTACHED TO AIRCRAFT DOCS). SERVICED HYD SYSTEM WITH NEW 5606. LEAK CHECK NORMAL. JACKED UP AIRCRAFT AND PERFORMED GEAR SWING CHECK, FOUND TO BE NORMAL.
2. REMOVED CABIN FLOOR CARPET AND INSTALLED NEW AIRTEX CABIN FLOOR CARPET.
3. REMOVED GARMIN GNS 430 PN 011-00280-10 SN 97112218 AND SENT OUT TO PENINSULA AVIONICS FOR REPAIRS. RECEIVED SAME UNIT FROM PENINSULA AVIONICS AND INSTALLED. (8130-3 ATTACHED TO AIRCRAFT DOCS). OPS CHECK NORMAL.
4. ALL WORK PERFORMED AS PER A/C MM.

DANIEL ESTEBAN POSADA

[REDACTED]
[REDACTED]

Photograph 1 - Hydraulic Pack Installation Entry in Aircraft Maintenance Log