



Photo 1 – Main wreckage, front view (FAA)



Photo 2 – wing, leading edge damage (FAA)



Photo 3 – Tail section, (FAA)