



# NTSB ERA23LA210 Piper PA30 | N751WW

Investigative Photographs



Photo 1: Overview of the airplane after recovery from the runway (Photo Courtesy of FAA)



Photos 2: Overview of the substantial damage sustained to the fuselage (Photo Courtesy of FAA)



Photos 3: Additional overview of the substantial damage sustained to the fuselage (Photo Courtesy of FAA)