



## **NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Eastern Region

**Photo Array**

**ERA23LA216**



**Photo 1 – Right Rear View of Accident Airplane (Courtesy of FAA)**




**Photo 2 – Closeup View of Damaged Left Wingtip (Courtesy of FAA)**



**Photo 3 – View of Damaged Elevator – Left Side. Note Missing Counterweight (Courtesy of FAA)**



**Photo 4 – View of Broken Left Landing Gear Lock. Wood For Support Post-Accident (Courtesy of FAA)**



**Photo 5 – View of Landing Gear Assembly, After Repairs. Arrow Points to Replaced Lock (Courtesy of Pilot)**