

ERA23LA218

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Side View of Airplane (Courtesy of Piper Aircraft Company)



Photograph 2 - Left and Right Wings (Courtesy of Piper Aircraft Company)



Photograph 3 - Left Side View of Airplane (Courtesy of Piper Aircraft Company)



Photograph 4 - Engine (Courtesy of Piper Aircraft Company)



Photograph 5 - Damage to the No. 4 cylinder/piston (Courtesy of FAA)



Photograph 6 - Large Hole in the Engine Case (Courtesy of FAA)



Photograph 7 - Oil Sump Screen and Metallic Debris Found in the Oil Sump (Courtesy of FAA)