


ERA23LA218


ENGINE PHOTOGRAPHS




Photograph 1 -Wear to Camshaft Lobes and Lifters (FAA)



Photograph 2 - Oil Filter Screen with Metallic Debris (FAA)



Photograph 3 - No. 2 Cylinder Piston Pin Plug Damage (Lycoming)



Photograph 4 - Internal Damage to Crankcase (Lycoming)