

ERA23LA245

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Tailwheel and Lower Rudder (Courtesy of FAA)



Photograph 3 - Tow Hook (Courtesy of FAA)



Photograph 4 - Propeller



Photograph 5 - Propeller Blade



Photograph 6 - Other Propeller Blade



Photograph 7 - Right Side of Lower Rudder and Tailwheel



Photograph 8 - Close Up of Right Side of Lower Rudder Showing Fractured Rudder Horn



Photograph 9 - Broken Right Rudder Horn and Extension



Photograph 10 - Top View of Broken Right Rudder Horn and Extension




Photograph 11 - Fracture Face on Right Rudder Horn and Extension



Photograph 12 - Bottom View of Broken Right Rudder Horn and Extension



Photograph 13 - Tow Hook Displaying Bent Prong



Photograph 14 - Close Up of Bent Prong



Photograph 15 - Close Up of Bend in Prong

END