



Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA259



Photo 1 – View of airplane from right wing (photo courtesy of FAA)



Photo 2 – View of firewall damage (photo courtesy of FAA)



Photo 3 – Close-up view of wrinkle in lower fuselage (photo courtesy of FAA)