

ERA23LA261

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of KEPC ARFF)



Photograph 2 - Left Wing and Engine (Courtesy of KEPC ARFF)



Photograph 3 - Right Wing and Engine (Courtesy of KEPC ARFF)



Photograph 4 - Right Wing and Empennage (Courtesy of KEPC ARFF)



Photograph 5 - Rear View (Courtesy of KEPC ARFF)




Photograph 6 - Left Rear View (Courtesy of KEPC ARFF)



Photograph 7 - Left Wing (Courtesy of KEPC ARFF)




Photograph 8 - Cockpit (Courtesy of KEPC ARFF)



Photograph 8 - Enhanced Cockpit Photo



Photograph 10 - T/R Emergency Stow Switches as Found Prior to Aircraft Recovery



Photograph 11 - Flap Handle



Photograph 12 - Air Brakes (Spoilers)



Photograph 13 - Thrust Levers



Photograph 14 - Top of Left Wing



Photograph 15 - Bottom of Left Wing



Photograph 16 - Top Midspan Portion of Right Wing



Photograph 17 - Top Outboard Portion of Right Wing



Photograph 18 - Nose Landing Gear




Photograph 19 - Frame 0 (Forward Pressurization Bulkhead)




Photograph 20 - 121AL Service Door (Pressurized)



Photograph 21 - Aft Right Corner of 121AL Service Door and Frame 1 (Pressurized)



Photograph 22 - Flight Safety Pilot Checklist



Photograph 23 - Flight Safety Pilot Checklist ("For Training Purposes Only")



Photograph 24 - Right Engine



Photograph 25 - Left Engine