

ERA23LA264

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Insurance Adjuster Digital Photograph Left Side View of the Airplane at the Accident Site



Photograph 2 - Digital Photograph From Recovery Company View of the Damaged Engine Mount