

ERA23LA277

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage aft of nose gear landing well (Courtesy FAA)



Photograph 2 - Nose Landing Gear Actuator Mount Structure (Courtesy of FAA)