

ERA23LA281

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damaged left wing strut. (Courtesy of FAA)



Photograph 2 - View of airplane damage at accident site before recovery. (Courtesy of FAA)



Photograph 3 - Right wing damage (Courtesy of FAA)