

ERA23LA283

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of aircraft at rest (Courtesy of FAA Inspector)



Photograph 2 - View of Engine (Courtesy of FAA Inspector)



Photograph 3 - View of propeller blades (Courtesy of FAA Inspector)