

ERA23LA285

INVESTIGATIVE PHOTOS



Photograph 1 - main wreckage on trailer



Photograph 2 - airplane on trailer by recovery company



Photograph 3 - Turbo charger fractured.