

NTSB ERA23LA291

PR-ZVL, Volato 400

Photo Array



Photo 1: Overview of the airplane at the accident site. (Photo Courtesy of FAA)



Photo 2: View of the damage to the firewall. (Photo Courtesy of FAA)



Photo 3: View of the damage to the firewall. (Photo Courtesy of FAA)



Photo 4: View of the autopilot servo bracket on the elevator control tube. (Photo Courtesy of FAA)