



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Investigative Photographs

ERA23LA292



Photo 1 – View of Accident Airplane (Courtesy of FAA)



Photo 2 – View of Engine Mount Damage (Courtesy of FAA)