

ERA23LA297

INVESTIGATION PHOTOGRAPHS



Photo 1: View of the airplane at the accident site nosed over (Photo Courtesy of FAA)



Photo 2: View of the airplane at the accident site nosed over (Photo Courtesy of FAA)



Photo 3: View of the cockpit at the accident site (Photo Courtesy of FAA)



Photo 4: View of the engine at the accident site (Photo Courtesy of FAA)



Photo 5: View of the top spark plugs (Photo Courtesy of FAA)



Photo 6: View of the engine filters (Photo Courtesy of FAA)



Photo 7: View of the partially disassembled carburetor (Photo Courtesy of FAA)