

ERA23LA300

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Ground scar leading up to airplane (Courtesy of MVY Airport Manager)



Photograph 2 - View of airplane from right wing (Courtesy of MVY Airport Manager)



Photograph 3 - View of airplane from front (Courtesy of MVY Airport Manager)



Photograph 4 - View of fractured left wing (Courtesy of MVY Airport Manager)