

ERA23LA310

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Impact separated right wing with main wreckage in background. (Courtesy of FAA)



Photograph 2 - Empennage (Courtesy of FAA)



Photograph 3 - View of wreckage as discovered. (Courtesy of FAA)



Photograph 4 - View of propeller and spinner. (NTSB)



Photograph 5 - View of Nos. 2 and 4 side with valve covers removed. (NTSB)