

ERA23LA311

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right side of airplane (Courtesy of FAA)



Photograph 2 - Right wing root showing damage (Courtesy of FAA)