

ERA23LA319

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Main Wreckage (Courtesy of FAA)**



**Photograph 2 - Main Wreckage (Courtesy of FAA)**



**Photograph 3 - Main Wreckage (Courtesy of FAA)**



**Photograph 4 - Empennage and Tail Rotor (Courtesy of FAA)**



**Photograph 5 - Tail Rotor Pitch Change Trunnion and Lever Assemblies (Courtesy of FAA)**



**Photograph 6 - Tail Rotor Pitch Change Trunnion and Lever Assemblies (Courtesy of FAA)**