

ERA23LA235

INVESTIGATION PHOTOGRAPHS



Photograph 1 –Airplane at Accident Site Inverted (Courtesy of Tyler Hodge)



**Photograph 2 – Fuel Staining Around Fuel Drain Valve on Right Wing
(Courtesy of Tyler Hodge)**



Photograph 3 – Fuel Staining on RH Flaperon (Courtesy of Tyler Hodge)