

ERA23LA333

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Propeller and Engine Compartment (Courtesy of FAA)



Photograph 2 - Main Wreckage (Courtesy of FAA)



Photograph 3 - Left Wing Damage (Courtesy of FAA)