

ERA23LA337

WRECKAGE PHOTOGRAPHS




Photograph 1 - Wreckage at accident site (Courtesy of FAA)



Photograph 2 - Wreckage at accident site (Courtesy of FAA)



Photograph 3 - Engine overview (Courtesy of Piper)



Photograph 4 - Fuel selector valve (Courtesy of Piper)



Photograph 5 - Fuel servo air inlet tube (Courtesy of Piper)




Photograph 6 - Fuel servo air inlet tube with hole (Courtesy of Piper)



Photograph 7 - Firewall wear from induction tube (Courtesy of Piper)



Photograph 8 - Fuel servo air inlet (Courtesy of Piper)



Photograph 9 - Fuel servo air inlet (Courtesy of Piper)



Photograph 10 - Fuel servo idle mixture linkage (Courtesy of Piper)



Photograph 11 - Fuel Servo Throttle Valve (Courtesy of Piper)