

ERA23LA338

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Missing Right Elevator (Courtesy of FAA)