

ERA23LA347

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Starter Motor Electrical Lead And Fuel Primer Line (Courtesy of FAA)



Photograph 3 - Tachometer (Courtesy of FAA)