

ERA23LA365

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane on the side of the lake after being recovered from the water. (Courtesy of FAA)



Photograph 2 - View of damage to the right wing and fuselage (Courtesy of FAA)



Photograph 3 - View of damage to the left side of the fuselage. (Courtesy of FAA)



Photograph 4 - View of the throttle quadrant. (Courtesy of FAA)




Photograph 5 - View of switches and circuit breakers. (Courtesy of FAA)



Photograph 6 - View of boost pump with fractured fuel line. (Courtesy of FAA)



Photograph 7 - View of boost pump with fractured fuel line. (Courtesy of FAA)



Photograph 8 - View of boost pump and fractured fuel line. (Courtesy of FAA)