

ERA23LA368

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of airplane (Courtesy of FAA Inspector)



Photograph 2 - Side view of wing damage (Courtesy of FAA Inspection)



Photograph 3 - Close view of wing damage. (Courtesy of FAA Inspector)