

ERA23LA374


INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of inverted airplane from left wing (Courtesy of FAA)



Photograph 2 - View of damaged empennage (Courtesy of FAA)



Photograph 3 - Closeup view of left wing damage (Courtesy of FAA)