

ERA23LA378

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of left side of airplane with collapsed nose landing gear. (Courtesy of Pilot)



**Photograph 2 - View of right side of airplane with closeup view of nose landing gear damage.
(Courtesy of Pilot)**



Photograph 3 - Closeup view of firewall puncture and engine mount damage (Courtesy of Savannah Aviation)