

ERA23LA383

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Main Wreckage (Courtesy of Airport Manager)



Photograph 2 - Engine Examination (Courtesy of AMF Aviation)



Photograph 3 - Top Spark Plugs (Courtesy of AMF Aviation)



Photograph 4 - Fuel Sample (Courtesy of AMF Aviation)



Photograph 5 - Carburetor (Courtesy of AMF Aviation)