

ERA23LA387

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overview of damage to the left wing. (Courtesy of FAA)



Photograph 2 - View of damage to the left wing leading edge. (Courtesy of FAA)



Photograph 3 - View of damage to the left wing. (Courtesy of FAA)



Photograph 4 - View of damage to the left horizontal stabilizer. (Courtesy of FAA)