

ERA24FA026

INVESTIGATIVE PHOTOS



Photograph 1 - Main wreckage



Photograph 2 - Left wing, Note: accordion crushing



Photograph 3 - Cabin and instrument panel



Photograph 4 - Tail view