

ERA24FA036

INVESTIGATION PHOTOGRAPHS



Photograph 1 – Accident site overview



Photograph 2 – Engine overview



Photograph 3 – Propeller blade



Photograph 4 – Vacuum pump after disassembly



Photograph 5 – Attitude indicator gyro after disassembly



Photograph 6 – Turn and bank indicator after disassembly



Photograph 7 - Tachometer