

ERA24FA050

INVESTIGATION PHOTOGRAPHS



Photograph 1 - NTSB Digital Photograph. View Looking From Main Wreckage Towards Impacted Trees



Photograph 2 - NTSB Digital Photograph. Left Side View of the Engine Assembly with Attached Propeller, Cockpit and Cabin Areas



Photograph 3 - NTSB Digital Photograph. View of the Aft Empennage Suspended in Tree



Photograph 4 - NTSB Digital Photograph. Frontal View of the Engine Assembly with Attached Propeller



Photograph 5 - NTSB Digital Photograph. View of the Right Wing



Photograph 6 - NTSB Digital Photograph. Left Side View of the Upright Engine Assembly with Attached Propeller After Removing Upper Engine Cowling



Photograph 7 - NTSB Digital Photograph. Frontal View of the Upright Engine Assembly with Attached Propeller Following Removal of the Upper Cowling



Photograph 8 - NTSB Digital Photograph. Right Side View of the Upright Engine Assembly with Attached Propeller Following Removal of the Upper Cowling




Photograph 9 - NTSB Digital Photograph. Left Side View of the Inverted Engine Assembly Following Removal of the Cowling



Photograph 10 - NTSB Digital Photograph. View Focused on the Remaining Portion of the Nose Landing Gear



Photograph 11 - NTSB Digital Photograph. Rear View of the Engine Assembly Following Removal of the Firewall




Photograph 12 - NTSB Digital Photograph. Arrow Points to Heat Damaged Left Magneto




Photograph 13 - NTSB Digital Photograph. Close-Up View of Heat Damaged Left Magneto



Photograph 14 - NTSB Digital Photograph. View of Heat Damaged Right Magneto



Photograph 15 - NTSB Digital Photograph. View of the Accessory Section of the Engine Following Removal of the Accessory Case



Photograph 16 - NTSB Digital Photograph. View of the Accessory Case Following Removal From the Engine



Photograph 17 - NTSB Digital Photograph. View of the Parts Retained For NTSB Metallurgical Examination




Photograph 18 - NTSB Digital Photograph. View of the Aft Empennage Following Wreckage Recovery



Photograph 19 - AMF Aviation Digital Photograph. View of the Left Magneto



Photograph 20 - AMF Aviation Digital Photograph. View of the Impulse Coupling End of Left Magneto



Photograph 21 - NTSB Digital Photograph. Annotated photograph depicting pieces of Impulse Coupling Rivet Found in Oil Sump