

ERA24FA069

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage



Photograph 2 - Instrument Panel



Photograph 3 - Wreckage Path



Photograph 4 - Wreckage Path



Photograph 5 - Wreckage Path



Photograph 6 - Doors and Sections of Cabin Interior Liners



Photograph 7 - Portions of Cabin Door



Photograph 8 - Tail Rotor Blade



Photograph 9 - Engine, Transmission, and Remains of Main Rotor Blades



Photograph 10 - Remains of Airframe after Recovery



Photograph 11 - Axial Compressor (Courtesy of Safran)



Photograph 12 - Power Turbine (Courtesy of Safran)



Photograph 13 - Input Pinion Slippage Mark Misalignment (Courtesy of Safran)