

ERA24FA078

INVESTIGATION PHOTOGRAPHS



Photograph 1 – Airplane overview at accident site




Photograph 2 – Airplane overview at accident site



Photograph 3 – Tree impact at accident site



Photograph 4 – Airplane overview at accident site



Photograph 5 – Induction tube with missing clamp