

ERA24FA088

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front Left View of Airplane at Accident Site



Photograph 2 - Right Front View of Airplane at Accident Site



Photograph 3 - Rear View of Airplane at Accident Site



Photograph 4 - Ice on Leading Edge of Left Wing (outboard)



Photograph 5 - Ice on Leading Edge of Right Wing (outboard)



Photograph 6 - Ice on Leading Edge of Left Horizontal Stabilizer



Photograph 7 - Ice on Leading Edge of Right Horizontal Stabilizer