

ERA24FA154

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane overview at accident site



Photograph 2 - Part of the airplane's left wing outboard section



Photograph 3 - Baggage door in the open position



Photograph 4 - Baggage door in the closed position



Photograph 5 - Main cabin door after partial disassembly



Photograph 6 - Main cabin door aft latch pin



Photograph 7 - Main cabin door aft striker plate



Photograph 8 - Main cabin door upper latch



Photograph 9 - Main cabin door upper latch pin