

ERA24FA176

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of main wreckage



Photograph 2 - View left wing



Photograph 3 - View of vertical stabilizer, rudder and horizontal stabilizer.



Photograph 4 - View of right-wing post examination



Photograph 5 - View of engine post-accident.