

ERA24FA217

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of cabin/fuselage showing latitude and longitude, elevation, and magnetic heading. (NTSB)



Photograph 2 - View of partial cabin/fuselage against tree. (NTSB)



Photograph 3 - View of field and wreckage. (NTSB)



Photograph 4 - View of separated left wing resting against fence. (NTSB)



Photograph 5 - View of engine after recovery. (NTSB)



Photograph 6 - View of aft passenger seat in field. (NTSB)



Photograph 7 - Elevator-rudder (ruddervator) located at beginning of wreckage path. (NTSB)



Photograph 8 - Recovered wreckage layout on hangar floor. (NTSB)



Photograph 9 - View of stabilator spar showing preimpact deformation damage. (NTSB)



Photograph 10 - View of wreckage looking from tail forward. (NTSB)



Photograph 11 - View of right wing and spar looking outboard. (NTSB)