

ERA24FA266

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aft view of airplane.



Photograph 2 - Left side view of airplane.



Photograph 3 - View of inside cockpit.



Photograph 4 - Close up view of loose B-Nut fitting hydraulic fluid leakage.



Photograph 5 -View of landing gear strut and brake line.



Photograph 6 - View of damaged underside of airplane.