

ERA24FA294

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial view of accident site and wreckage (Courtesy of North Carolina State Police)



Photograph 2 - Remains of the fuselage with tail and wing sections. (Courtesy of NTSB)



Photograph 3 - Empennage with damaged structure, damaged left horizontal stabilizer and elevator and wrinkling of the vertical stabilizer. (Courtesy of NTSB)



Photograph 4 - Left wing with leading edge, tip and root damage, damaged aileron and crushed flap. (Courtesy of NTSB)



Photograph 5 - Left wing with leading edge, tip and root damage, damaged aileron and crushed flap. (Courtesy of NTSB)