

ERA24FA310

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Airplane at accident site



Photograph 2 - Engine at accident site




Photograph 3 - Propeller gearbox at accident site



Photograph 4 - Propeller governor on test bench (Courtesy of Hartzell)



Photograph 5 - Propeller blades (Courtesy of Hartzell)



Photograph 6 - Propeller hub (Courtesy of Hartzell)



Photograph 7 - Propeller piston (Courtesy of Hartzell)




Photograph 8 - Engine after recovery




Photograph 9 - No. 3 intake valve missing one valve key



Photograph 10 - No. 1 piston with valve strike impressions



Photograph 11 - No. 1 cylinder head with valves



Photograph 12 - Propeller gearbox after disassembly