

ERA24FA371

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wreckage overview at the accident site



Photograph 2 - Wreckage overview at the accident site



Photograph 3 - Flap control bar




Photograph 4 - Screenshot of accident takeoff (Courtesy of: Witness)



Photograph 5 - Piece of wood at accident site with 45° cut



Photograph 6 - Tachometer



Photograph 7 - Engine alternate air door control



Photograph 8 - Alternate air door



Photograph 9 - Engine's spark plugs



Photograph 10 - Engine overview after recovery



Photograph 11 - Fuel injection servo



Photograph 12 - Fuel injection throttle stop pin