

ERA24LA004

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Upper Wing Damage (Courtesy of FAA)



Photograph 2 - Vertical Stabilizer and Rudder Damage (Courtesy of FAA)