

ERA24LA007

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane overview (Courtesy of FAA)



Photograph 2 - Airplane overview (Courtesy of Cirrus)



Photograph 3 - Damage to the right wing (Courtesy of Cirrus)




Photograph 4 - Damage to the left wing (Courtesy of Cirrus)



Photograph 5 - Impact damaged tree (Courtesy of Cirrus)



Photograph 6 - PFD, MFD, and MD302 operating after accident (Courtesy of FAA)



Photograph 6 - Pitot tube with tree material plugging the pitot hole (Courtesy of Cirrus)